

Information note

Topic SARA-N310-00X product version initial production

UBX-20033555 C1-Public

Author Samuele Falcomer

Date 14-Oct-2020

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited, with respect to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit www.u-blox.com. Copyright® u-blox AG.

1 Affected products

Product name	Ordering code	Type number	Firmware	Remarks
SARA-N310	SARA-N310-00X	SARA-N310-00X-00	Modem:	18.13
			Application:	A01.00

2 Type

\boxtimes	Product status change	\boxtimes	Documentation update
	Hardware/component change		Certification information
\boxtimes	Firmware/software update		Security advisory
	Label change		Other

3 Description

Status of the above listed products has changed from engineering samples (ES) to initial production (IP). For the details of the new features and improvements implemented in the IP version, see Appendix A.

4 Schedule

First production parts will be available in calendar week 42/43.

Product name	Ordering code	Available from	
SARA-N310	SARA-N310-00X	CW42	
EVK-N310	EVK-N310-0	CW43	
ADP-N310	ADP-N310-0	CW43	

5 Customer impact and recommended actions

- We recommend customers with engineering samples 2 (ES2) to update the engineering sample units to initial production firmware.
- Initial production firmware version is required for new devices entering certification labs.

6 Firmware update

- It is not possible to upgrade early samples, prototype, and engineering sample 1 (ES) units to the initial production firmware.
- Engineering sample 2 (ES2) can be updated to initial production firmware by means of EasyFlash v12.08, FOAT, FOTA or uFOTA.



6.1 Firmware update packages and md5 signature

Product / delivery	Filename	md5sum
SARA-N310		
FOTA ES2 to IP SARA-N310-00X-00_FW18.10_A01.04_ES2SARA- uFOTA ID: 925 N310-00X-00_FW18.13_A01.00_IP.pack		3d4747bb158259c6ce13ec7f5a03fcf7
EasyFlash	SARA-N310-00X-00_FW18.13_A01.00.dof	3ea281e611d488b0dc06222905e4ad22
FOAT	SARA-N310-00X-00_FW18.10_A01.04_ES2SARA- N310-00X-00_FW18.13_A01.00_IP.pack	3d4747bb158259c6ce13ec7f5a03fcf7
FOTA (test) uFOTA ID: 926	SARA-N310-00X-00_FW18.13_A01.00_IPSARA-N310- 00X-00_FW18.13_A01.00_FOTA.pack	98787c2070665da3989192033e691c64
FOTA (test) uFOTA ID: 927	SARA-N310-00X-00_FW18.13_A01.00_FOTASARA- N310-00X-00_FW18.13_A01.00_IP.pack	a451ca41ffa3bdec59883b44f636cdd2

7 Tools

- m-center v02.03.00 Download from the u-blox.com website via this page: m-center
- EasyFlash 12.08 Download from the u-blox.com website via this link: EasyFlash 12-08

8 Related documentation

- [1] SARA-N2 / SARA-N3 series AT commands manual, <u>UBX-16014887</u>
- [2] SARA-N3 series data sheet, UBX-18066692
- [3] SARA-N2 / SARA-N3 series system integration manual UBX-17005143

Appendix

A Features added compared to engineering samples

- Radio Policy Manager (RPM)
- Network attach optimizations
- FTP fixes and optimizations
- Cipher suites added for TLS/DTLS
- RX test mode (<mode>=2) and TX test mode (<mode>=3) on the +UTEST AT command
- MQTT: increased <client_id>, <username>, <password> parameter length to 256 bytes

B Known bugs and limitations

- [u-blox id 736] +UJAD AT command: the registration status may not get updated after a jamming is detected.
- [u-blox id 798] SMS: UTF-16 encoding is not supported.
- [u-blox id 795] SMS: special 7-bit characters are not properly decoded at reception.
- [u-blox id 791] +CPIN AT command: after providing PIN1, the module does not perform attach automatically. A manual attach must be triggered after providing PIN1.
- [u-blox id 733] The +CRSM AT command does not return correct values.
- [u-blox id 504] uFOTA: file download progress cannot be tracked. Notification of success or failure is given at the end of FOTA package download process.
- [u-blox id 810] CoAP: error result code from the CoAP server is not reported to user via URC.