

IN – Information Note

Topic:	LEON-G100, SARA-G310/G350, LISA-U200/U201, TOBY-L200/L280, MPC-I-L200/L280 label change
	UBX-17003070
Author:	Rado Sustersic
Date:	15-Feb-2017

We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express permission is strictly prohibited.

© 2017 u-blox ag.

1 Affected Products


Product Name	Order Number	Type No	Remarks
LEON-G100	LEON-G100-06S	LEON-G100-06S-02	
LEON-G100	LEON-G100-07S	LEON-G100-07S-01	
LEON-G100	LEON-G100-08S	LEON-G100-08S-01	
SARA-G310	SARA-G310-00S	SARA-G310-00S-01	
SARA-G350	SARA-G350-00S	SARA-G350-00S-00	
SARA-G350	SARA-G350-01S	SARA-G350-01S-00	
SARA-G350	SARA-G350-02S	SARA-G350-02S-00	
LISA-U200	LISA-U200-01S	LISA-U200-01S-01	
LISA-U200	LISA-U200-02S	LISA-U200-02S-01	
LISA-U200	LISA-U200-03S	LISA-U200-03S-00	
LISA-U201	LISA-U201-03S	LISA-U201-03S-00	
TOBY-L200	TOBY-L200-00S	TOBY-L200-00S-01	
TOBY-L280	TOBY-L280-02S	TOBY-L280-02S-00	
MPCI-L200	MPCI-L200-00S	MPCI-L200-00S-01	
MPCI-L280	MPCI-L280-02S	MPCI-L280-02S-00	

2 Type of Change

- Hardware modification
- Firmware update
- Documentation update
- Label change

3 Description of Change

The labels placed on the products listed above have changed in order to be compliant with the ANATEL requirements. To the ANATEL homologation number, two 0s have been added; see the drawings below:

LEON Label:**SARA label:****LISA Label:****TOBY Label:**

4 Schedule

Immediate

5 Customer Impact and Recommended Action

None

6 Reference Documents

- [1] SARA-G3 Series Data Sheet, u-blox document UBX-13000993
- [2] LEON-G100 Data Sheet, u-blox document UBX-13004887
- [3] LISA-U2 Series Data Sheet, u-blox document UBX-13001734
- [4] TOBY-L2 Series Data Sheet, u-blox document UBX-13004573
- [5] MPC1-L2 Series Data Sheet, u-blox document UBX-13004749