

IN – Information Note

Topic:	MAX-8 and MAX-M8 Documentation Update
	UBX-17006257
Author:	uple
Date:	March 03, 2017

We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express permission is strictly prohibited.

© 2017 u-blox ag.

1 Affected Products

Product Name	Order Number	Type No	Firmware version	Remarks
MAX-M8C	MAX-M8C-0	MAX-M8C-0-10	ROM SPG 3.01	
MAX-M8Q	MAX-M8Q-0	MAX-M8Q-0-10	ROM SPG 3.01	
MAX-M8W	MAX-M8W-0	MAX-M8W-0-10	ROM SPG 3.01	
MAX-8Q	MAX-8Q-0	MAX-8Q-0-10	ROM SPG 3.01	
MAX-8C	MAX-8C-0	MAX-8C-0-10	ROM SPG 3.01	

2 Type of Change

- Hardware modification
- Firmware update
- Documentation update – Hardware Integration Manual
- Others:

3 Description of Change

MAX-8M / MAX-M8 Hardware Integration Manual has been updated:

- Section 2.4.6: Power, short and open detection Antenna Supervisor (MAX-M8W)

4 Customer Impact and Recommended Action

It is recommended that customers acquire the latest documentation and check for potential changes / updates. Affected document [1] contains a revision history with information about the content changes.

5 Reference Document

[1] [MAX-8 / MAX-M8 \(FW3\) Hardware Integration Manual \(UBX-15030059\)](#)