

IN – Information Note

Topic:	OBS421-01B Information Note
	UBX-15015470
Author:	pber
Date:	12-May-2015

We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express permission is strictly prohibited.

© 2015 u-blox ag.

1 Affected Products

Product Name	Ordering Code	Type No	Remarks
OBS421I	CB-OBS421I-24-01B	CB-OBS421I-24-01B-00	
OBS421X	CB-OBS421X-24-01B	CB-OBS421X-24-01B-00	
OBS421I	CB-OBS421I-i4-01B	CB-OBS421I-i4-01B-00	
OBS421X	CB-OBS421X-i4-01B	CB-OBS421X-i4-01B-00	

2 Type of Change

- Hardware modification
- Firmware update
- Documentation update

3 Description of Change

Two information notes have been sent informing about the availability of firmware v5.3.1 and firmware v5.1.0. The information was sent in the following INs:

1. [OBS421-24-01B_IN_\(UBX-15013632\)](#)
2. [OBS421-i4-01B_IN_\(UBX-15013713\)](#)

A minor bug with effect on the produceability has been found in the dual mode firmware v5.3.1 and in the iAP firmware v5.1.0. No shipments have been made with firmware v5.3.1 or v5.1.0 and the affected products will use an updated firmware version. This has also caused a delay on the availability. For details regarding the latest firmware, please navigate to the firmware download pages.

[cB-OBS421 Dual Mode Firmware](#)

[cB-OBS421 iAP Firmware](#)

4 Schedule

Estimated first download date: 18-May-2015

Estimated first shipment date for samples: 1-June-2015

5 Customer Impact and Recommended Action

Customers are encouraged to evaluate the new firmware before placing orders with the new ordering codes.