

## PCN – Product Change Notification

|                 |   |
|-----------------|---|
| <b>Topic :</b>  | <b>Rollout of Firmware Release 5.00</b> |
|                 | UBX-TN-06008-A                          |
| <b>Author :</b> | GzB                                     |
| <b>Date :</b>   | April 21, 2006                          |

We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express authority is strictly forbidden.

© 2006 u-blox ag.

### 1 Affected Products

| Technology | Product Name | Order Number   | Data Code (Old)  | Data Code (New) | Remarks |
|------------|--------------|----------------|------------------|-----------------|---------|
| ANTARIS 4  | RCB-LJ-0     | RCB-LJ-0-000-x | ≤230100.2021.000 | 230100.2030.000 |         |
|            | RCB-LJ-1     | RCB-LJ-1-000-x | ≤230101.2021.000 | 230101.2030.000 |         |

### 2 Type of Change

- Hardware modification
- Firmware update
- Others, \_\_\_\_\_

### 3 Description of Change

u-blox has recently released the ANTARIS GPS Firmware 5.0 for both ANTARIS and ANTARIS 4 GPS products. This firmware contains significant improvements in navigation performance, new features as well as bug fixes. The new firmware will be rolled out in GPS products containing Flash EPROM.

Details are summarized in the release notes [1].

### 4 Schedule

The rollout of the new firmware in module production will begin in May 2006. Delivery of these products with new firmware will begin after the stocks of previously manufactured products have been cleared.

### 5 Customer Impact and Recommended Action

The GPS firmware 5.00 is backward compatible to its predecessors V3.0x. Customers in possession of older receiver boards may obtain the firmware image from u-blox. Please contact your local FAE for details.

### 6 Reference Documents

- [1] ANTARIS GPS Firmware Version 5.00, GPS.G4-SW-06000