

Product Change Notification

Topic LARA-R220 Firmware Update
UBX-18050698

Author Drazen Drinic

Date 20-Aug-2018

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited, with respect to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit www.u-blox.com.
Copyright© u-blox AG.

1 Affected Products

Product Name	Order Number	Type No (Old)	Type No (New)	Remarks
LARA-R220	LARA-R220-62B	LARA-R220-62B-00	LARA-R220-62B-01	

2 Type of Change

- Hardware modification
- Firmware update
- Documentation update
- Others

3 Description of Change

- [u-blox ID LR28002B-7] Under very rare circumstances, some units may lose their valid unique IMEI / calibration data over their lifetime. Without valid IMEI the module is unable to connect to the network. The new firmware provides a backup function in order to be able to restore lost IMEI / calibration data in case that happens.

The firmware version can be identified according to the type number, as follows:

Old type number	Current firmware version	New type number	New firmware version
LARA-R220-62B-00	Modem: 30.44 Application: A01.03	LARA-R220-62B-01	Modem: 30.44 Application: A01.04

The modem and application version can be polled from the module by sending the AT+GMR and AT+I9 commands. See the u-blox cellular AT commands manual [1] for details. The firmware is fully tested and has passed all the release tests at u-blox.

4 Schedule

Estimated First Shipment Date	31-Aug-2018
--------------------------------------	-------------

5 Customer Impact and Recommended Action

Products with the new type number are functionally and pin-to-pin compatible with their predecessors. Changes implemented in the new firmware are not relevant to certification, and certification grants already achieved remain valid.

6 Known limitation

See the LARA-R220-62B IP Information Note [5].

7 Reference Documents

- [1] u-blox AT Commands Manual (UBX-13002752)
- [2] LARA-R2 series System Integration Manual (UBX-16010573)
- [3] LARA-R2 series Data Sheet (UBX-16005783)
- [4] TOBY-R200, TOBY-R202, LARA-R202, LARA-R203, LARA-R280 Product Change Notification (UBX-18018067)
- [5] LARA-R220-62B IP Information Note (UBX-17061668)