

## Product Change Note

**Topic** MPCII-L200 / MPCII-L201/ MPCII-L210/ MPCII-L220/ MPCII-L280 packaging change  
UBX-17056200

**Author** Drazen Drinic

**Date** 23-May-2018

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit [www.u-blox.com](http://www.u-blox.com).  
Copyright© u-blox AG.

### 1 Affected Products

Product Name	Order Code
MPCII-L200	MPCII-L200-02S, MPCII-L200-03S
MPCII-L201	MPCII-L201-01S, MPCII-L201-02S
MPCII-L210	MPCII-L210-02S, MPCII-L210-03S, MPCII-L210-60S
MPCII-L220	MPCII-L220-02S, MPCII-L220-62S
MPCII-L280	MPCII-L280-02S, MPCII-L280-03S

### 2 Type of Change

- Hardware modification
- Firmware update
- Documentation update
- Packaging change

### 3 Description of Change

Packaging change: number of MPCII-L2 modules per tray changed from 32 to 16.

### 4 Schedule

Samples:	
Estimated First Shipment Date <sup>1</sup>	14-Sep-2018
Documentation (e.g. release note)	Available

### 5 Customer Impact and Recommended Action

None.

### 6 Reference Documents

- [1] MPCII-L2 Data Sheet, u-blox Document UBX-13004749-R20
- [2] u-blox Package Information, u-blox Document UBX-14001652

<sup>1</sup> The Estimated First Shipment Date is the forecasted date that a customer may expect to receive changed product with the new Type Number. This is determined by the estimated date of inventory depletion on the PCN issue date. This may be affected by fluctuations in supply and demand. Consequently, although customers should be prepared to receive changed product on this date, u-blox will continue to ship pre-changed product until a time in which inventory has been depleted. This may result in pre-changed product being shipped to customers after this forecasted date.