

IN – Information Note

Topic:	UBX-M8030 Data Sheet (UBX-14002333) update for UBX-M8030-CT chip
	UBX-15029637
Author:	uple
Date:	November 19, 2015

We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express permission is strictly prohibited.

© 2015 u-blox ag.

1 Affected Products

Product Name	Order Number	Type No	Remarks
UBX-M8030-CT	UBX-M8030-CT	UBX-M8030-CT-B2000A	UBX-M8030-CT pin correction in Table 9 (Power Management)

2 Type of Change

- Hardware modification
- Firmware update
- Documentation update
- Others :

3 Description of Change

The UBX-M8030 Data Sheet [1] has been changed

- In respect to UBX-M8030-CT pin naming (A6, A7) description in Power Management (Table 9).
 - V_DCDC_IN: Ball A6
 - V_DCDC_OUT: Ball A7
- Updated Table 1, added specification for TIMEPULSE2 (0.25 Hz to 1 kHz)
- Revised SPI timing recommendations in sections 3.2.3 and 7.4.1.

4 Schedule

The release of an updated Data Sheet [1] is with immediate effect. The new Data Sheet [1] contains a revision history with information about the changes and can be recognized by document revision statement on page 2:

Old: Revision R04, date 27-Oct-2014

New: **Revision R05, date 19-Nov-2015**

5 Reference Document

[1] UBX-M8030 Data Sheet, Docu. No. UBX-14002333