

## Information Note

**Topic** ZOE-M8 status change from IP to MP and documentation update

UBX-18021352

**Author** fbou

**Date** 23 July 2018

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited, with respect to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit [www.u-blox.com](http://www.u-blox.com). Copyright© u-blox AG.

## 1 Affected Products

Product Name	Order Number	Type No	Firmware	Remarks
ZOE-M8G	ZOE-M8G-0	ZOE-M8G-0-10	ROM SPG 3.01 / Flash FW SPG3.01	
ZOE-M8Q	ZOE-M8Q-0	ZOE-M8Q-0-10	ROM SPG 3.01 / Flash FW SPG3.01	

## 2 Type of Change

- Hardware modification
- Firmware update
- Documentation update
- Others

## 3 Description of Change

As the u-blox ZOE-M8G and ZOE-M8Q concurrent GNSS receiver SiPs have changed status from IP (Initial Production) to MP (Mass Production), the following documents have been updated to reflect the latest product information:

- ZOE-M8 Data Sheet
  - Status changed from Early Production Information to Production information
- ZOE-M8 Hardware Integration Manual
  - Status changed from Early Production Information to Production information
  - Updated Appendix A3 section (with optional SQI Flash support)

## 4 Customer Impact and Recommended Action

It is recommended that customers acquire the latest documentation and check for potential changes / updates. Each affected document ([1], [2]) contains a revision history with information about the content changes.

## 5 Reference Documents

[1] ZOE-M8 Data Sheet (UBX-16008094)

[2] ZOE-M8 Hardware Integration Manual (UBX-16030136)