

## IN – Information Note

<b>Topic:</b>	<b>LEA-M8S BeiDou performance</b>
	UBX-14041103
<b>Author:</b>	uple
<b>Date:</b>	September 29, 2014

We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express permission is strictly prohibited.

© 2014 u-blox ag.

### 1 Affected Products

Product Name	Order Number	Type No	Remarks
LEA-M8S	LEA-M8S-0	LEA-M8S-0-00	

### 2 Type of Change

- Hardware modification
- Firmware update
- Documentation update
- Others : Wrong SAW filter mounted

### 3 Description of Change

The first production batch of LEA-M8S has been equipped with a SAW filter not fully suitable for BeiDou reception. Users running the module with use of BeiDou will experience reduced BeiDou reception. For customers using the module for GPS/GLONASS reception, there will be no performance degradation.

### 4 Schedule

New LEA-M8S modules will become available by mid-October, and can be identified by data code **180800.0400.000**. Old modules can be identified by data code **180800.0300.000**.

### 5 Customer Impact and Recommended Action

The number of LEA-M8S modules in the field is limited. If you use the module for BeiDou reception, please contact your local Sales Support.