

IN- Information Note

Topic:	LISA-U2 products release to Initial Production
	UBX-18006049
Author:	Rado Sustersic
Date:	19 th January 2018

We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express permission is strictly prohibited.

© 2016 u-blox ag.

1 Affected Products

Product Name	Order Number (unchanged)	Type No	Firmware	Remarks
LISA-U200	LISA-U200-01S	LISA-U200-01S-02	22.40 A01.02	Status: Initial Production
	LISA-U200-02S	LISA-U200-02S-02	22.90 A01.03	Status: Initial Production
	LISA-U200-03S	LISA-U200-03S-01	23.41 A01.04	Status: Initial Production
	LISA-U200-52S	LISA-U200-52S-02	22.86 A01.03	Status: Initial Production
	LISA-U200-62S	LISA-U200-62S-03	22.90 A01.03	Status: Initial Production
LISA-U201	LISA-U201-03S	LISA-U201-03S-01	23.41A01.04	Status: Initial Production
	LISA-U201-83S	LISA-U201-83S-01	23.41 A01.04	Status: Initial Production
LISA-U230	LISA-U230-01S	LISA-U230-01S-02	22.40 A01.02	Status: Initial Production
LISA-U260	LISA-U260-01S	LISA-U260-01S-03	22.61 A01.05	Status: Initial Production
	LISA-U260-02S	LISA-U260-02S-03	22.90 A01.04	Status: Initial Production
LISA-U270	LISA-U270-02S	LISA-U270-02S-03	22.90 A01.04	Status: Initial Production
	LISA-U270-62S	LISA-U270-62S-07	22.93 A01.07	Status: Initial Production
	LISA-U270-63S	LISA-U270-63S-01	22.93 A01.07	Status: Initial Production
	LISA-U270-68S	LISA-U270-68S-01	22.93 A01.07	Status: Initial Production

2 Type of Change

- Hardware modification
- Firmware update
- Documentation update
- Design status changed from "Engineering Sample" to "Initial Production"

3 Description of Change

Release to Initial Production of the following LISA-U2 modules:

Product Name	Order Number (unchanged)
LISA-U200	LISA-U200-01S
	LISA-U200-02S
	LISA-U200-03S

Product Name	Order Number (unchanged)
	LISA-U200-52S
	LISA-U200-62S
LISA-U201	LISA-U201-03S
	LISA-U201-83S
LISA-U230	LISA-U230-01S
LISA-U260	LISA-U260-01S
	LISA-U260-02S
LISA-U270	LISA-U270-02S
	LISA-U270-62S
	LISA-U270-63S
	LISA-U270-68S

For restrictions compared to specifications refer to **Error! Reference source not found., Error! Reference source not found., Error! Reference source not found., Error! Reference source not found., Error! Reference source not found., Error! Reference source not found., Error! Reference source not found., [8]** and [9]

For known bugs and limitation refer to **Error! Reference source not found., Error! Reference source not found., Error! Reference source not found., Error! Reference source not found., Error! Reference source not found., Error! Reference source not found., Error! Reference source not found., [8]** and [9]

4 Schedule

This information is effective as of 19th January, 2018.

5 Customer Impact and Recommended Action

N/A

6 Reference Documents

- [1] LISA-U2xx-02S, -U200-52S, -U200-62S, -U270-62S PCN, u-blox document UBX-14005768
- [2] LISA-U2xx-x3S, SARA-U2xx-03S modules Initial Production, u-blox document UBX-15020745
- [3] LISA-U200-62S-01 PCN, u-blox document UBX-16017712
- [4] LISA-U201-83S Initial Production IN, u-blox document UBX-16006079
- [5] LISA-U2xx-01S Initial Production Information Note, u-blox document UBX-TN-12040
- [6] LISA-U260 / LISA-U270 PCN, u-blox document UBX-14042086
- [7] LISA-U270-62S PCN, u-blox document UBX-16009934
- [8] LISA-U270-62S-05 PCN, u-blox document UBX-16010383
- [9] LISA-U270-68S IN, u-blox document UBX-15019240
- [10] LISA-U2 series PCN, u-blox document UBX-17048820