

Information Note

Topic u-blox connectivity software 6.0.1 available for ODIN-W2
UBX-18 063512

Author Erik Carlberg

Date 27 November 2018

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit www.u-blox.com.
Copyright© u-blox AG.

1 Affected Products

Product Name	Remarks
ODIN-W260	Software version 6.0.1 available
ODIN-W262	Software version 6.0.1 available

2 Type of Change

- Hardware modification
- Software update
- Documentation update
- Others

3 Description of Change

The u-blox connectivity software version 6.0.1 for ODIN-W2 includes correction of issues from the previous software releases. Corrected issues include the bridge mode, Wi-Fi scanning, as well as general stability improvements. The complete description of the new software version is provided in the release notes [1].

4 Schedule

The version 6.0.1 of u-blox connectivity software for ODIN-W2 is available for download from the web [2].

5 Customer Impact and Recommended Action

The new software version is compatible with its predecessor both in terms of APIs and behavior. Customers are recommended to migrate to the latest version to ensure best performance and stability of the Wi-Fi and Bluetooth connections.

6 Reference Documents

- [1] [Release Notes - u-blox Connectivity Software 6.0.1 for ODIN-W2](#)
- [2] [u-blox Connectivity Software 6.0.1 for ODIN-W2](#)