

## Information Note

**Topic** UBX-G8020, UBX-M8030 Data Sheet update

UBX-19010805

**Author** JunJun Lu

**Date** 15 March 2019

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited, with respect to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit [www.u-blox.com](http://www.u-blox.com).  
Copyright© u-blox AG.

## 1 Affected Products

Product Name	Order Code	Type No	Firmware	Remarks
UBX-G8020-KT	UBX-G8020-KT	UBX-G8020-KT-B3007A	ROM SPG 3.01	
UBX-M8030-KT	UBX-M8030-KT	UBX-M8030-KT-B3000A	ROM SPG 3.01 / FLASH FW SPG 3.01	
UBX-M8030-KA	UBX-M8030-KA-B3000A	UBX-M8030-KA-B3000A	ROM SPG 3.01 / FLASH FW SPG 3.01	
UBX-M8030-CT	UBX-M8030-CT-B3000A	UBX-M8030-CT-B3000A	ROM SPG 3.01 / FLASH FW SPG 3.01	
UBX-M8030-KT-DR	UBX-M8030-KT-B2003A	UBX-M8030-KT-B2003A	ROM 2.01 / FLASH ADR4.21	
UBX-M8030-KA-DR	UBX-M8030-KA-B2003A	UBX-M8030-KA-B2003A	ROM 2.01 / FLASH ADR4.21	
UBX-M8030-KA-DR	UBX-M8030-KA-B300BA	UBX-M8030-KA-B300BA	ROM SPG3.01 / FLASH ADR4.21	

## 2 Type of Change

- Hardware modification
- Firmware update
- Documentation update
- Others

## 3 Description of Change

In striving to provide u-blox customers with the best documentation and technical support, u-blox documentation is updated on a regular basis as needed.

The UBX-G8020, UBX-M8030 (FW3), and UBX-M8030-Kx-ADR4-2 Data Sheets (refer to [Reference Documents](#)) have been updated. The primary changes are:

- Updated -Kx chip (QFN40 package) mechanical drawing (fixed pin length typo)
- Updated VDD\_ANA, VDD\_LNA value in "Absolute maximum ratings Table"
- Updated section 9.2 (Approvals) with RoHS 2015 statement
- Rebranding

#### **4 Customer Impact and Recommended Action**

It is recommended that customers acquire the latest documentation and check for potential changes / updates. Each affected document ([1], [2], and [3]) contains a revision history with information about the content changes.

#### **5 Reference Documents**

- [1] UBX-G8020 Data Sheet (UBX-16005907)-Confidential (NDA required), Rev. R05
- [2] UBX-M8030 FW3 Data Sheet (UBX-15030040)-Confidential (NDA required), Rev. R05
- [3] UBX-M8030-Kx-ADR4-2 Data Sheet (UBX-18016378)-Confidential (NDA required), Rev. R03