

IN – Information Note

Topic:	LEA-M8S AADET_N reverse input polarity
	UBX-14042123
Author:	uple
Date:	October 30, 2014

We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express permission is strictly prohibited.

© 2014 u-blox ag.

1 Affected Products

Product Name	Order Number	Type No	Remarks
LEA-M8S	LEA-M8S-0	LEA-M8S-0-00	

2 Type of Change

- Hardware modification
- Firmware update
- Documentation update
- Others : Reverse polarity of AADET_N

3 Description of Change

The first production batch of LEA-M8S has a wrong default input polarity setting of the Active Antenna Detection (AADET_N). Customers not using this input for antenna detection will not be affected.

4 Schedule

Modules affected can be identified by the old data code 180800.0400.000. New modules will become available shortly with date code 180800.0500.000.

5 Customer Impact and Recommended Action

For customers who have modules with the old data code and are using the AADET_N, please contact your local Sales representative for support. Field update is possible.