

## PCN – Product Change Notification

<b>Topic:</b>	<b>LISA-U200-01S firmware change</b>
	UBX-14006181
<b>Author:</b>	este
<b>Date:</b>	30 <sup>th</sup> June 2014

We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express permission is strictly prohibited.

© 2012 u-blox ag.

### 1 Affected Products

Product Name	Order Number	Type No (Old)	Type No (New)	Remarks
LISA-U200	LISA-U200-01S	LISA-U200-01S-00	LISA-U200-01S-50	

### 2 Type of Change

Hardware modification

Firmware update

Others, \_\_\_\_\_

### 3 Description of Change

The firmware of the module has been modified to introduce an improvement to the file-system activities during power-off sequence, and reduces the risk of corruption of the internal file-system.

The firmware number is 22.4 (not changed). The firmware version can be polled from the module by sending an AT+GMR command. See AT commands manual [1] for details.

Module hardware remains unchanged.

### 4 Schedule

Samples:	Available
Estimated First Shipment Date :	Now
Documentation:	Available

### 5 Customer Impact and Recommended Action

Changes are not relevant for approvals and certifications.

u-blox has taken utmost care to ensure full backward compatibility to the previous versions. A system check before deployment in production is however still recommended.

### 6 Reference Documents

- [1]. u-blox AT Commands Manual Document UBX-13002752, Revision R21
- [2]. LISA-U2 series Data Sheet Document UBX-13001734, Revision R13
- [3]. LISA-U series System Integration Manual document UBX-13001118, Revision R17
- [4]. LISA-U200-61S Information Note Initial Production (UBX-TN-13019)